Applied Stream Science

Jane Archer

Project Manager

Louisville District

Patricia A. Grace-Jarrett, Ph. D.

Senior Project Manager

Louisville District

Jennifer C. Thomason

Project Manager

Louisville District



November 12, 2013

R

US Army Corps of Engineers
BUILDING STRONG®



Applied Stream Overview

 Stream Facts, regulatory Review & Stream Definition

- Examples of Degraded Streams
- Sources of Stream Impacts
- Compensating for Stream Impacts Stream Restoration

Kentucky Stream Facts:

- Kentucky has approximately 90,000 miles of mapped streams
- Second only to Alaska in navigable stream miles

- Only state in the U.S. bordered by major rivers on three sides:
 - Mississippi, Ohio, and Big Sandy Rivers




Regulatory Review & Stream Definition



Regulatory - Review

- Jurisdictional Determinations
- Issue permits:
 - ► Section 404 CWA
 - ► Section 10 R & H Act 1899
- Compliance/Enforcement






Regulatory Definition

Bed

Bank

OrdinaryHigh WaterMark





Degraded Streams: The good, the bad & the ugly...



Degraded Streams Ephemeral



BUILDING STRONG®

Degraded Streams Intermittent Streams









Degraded Streams Perennial Streams



Sources of Impacts



Culverts & Piping







Channelization







Detention/Retention



Relocation





BUILDING STRONG_®

Bank Hardening



Fill/Grading & Dumping








Agriculture





Concrete Lining







Crossings







Locks & Dams






BUILDING STRONG®

Bridges









Compensating for Stream Impacts: Stream Restoration



Compensating for Stream Impacts Stream Restoration







Ohio River Watershed: Florence Golf Course Stream Restoration

- 4.4 AC Pond Removal
- 2,500 LF of Stream (P + I) Restoration: floodplain & stream re-establishment & enhancement, culvert removal, bank stabilization
- Riparian Habitat Restoration



Stream Restoration



Ohio River Watershed: Boone Woods Stream & Wetland Restoration

- 0.1 AC Wetland Restoration
- 4,500 LF Stream (P, I E) Restoration: re-establishment, bank stabilization, riparian restoration
- Riparian Habitat Restoration



Stream Restoration



Licking River Watershed: Joe's Creek Stream Restoration

- 0.8 AC Wetland Restoration
- 2,500 LF Stream (P + E) Restoration: watershed, floodplain & stream reestablishment & enhancement
- Riparian Habitat Restoration











Ohio River Watershed: Adair WMA Stream and Wetland Restoration.

- 0.34 AC Wetland Restoration
- 6,600 LF of Stream (P + I) Restoration: stream re-establishment & enhancement,
- Riparian Habitat Restoration





- 1.5 AC Wetland Restoration
- 10,500 LF Stream (P, I & E)
 Restoration: Re-establishment & enhancement
- 5.0 AC Riparian Habitat Restoration







Kentucky River Watershed: Mill Creek Elementary Stream & Wetland Restoration

- 0.1 AC Wetland Restoration
- 700 LF Stream (I &E) Restoration: aquifer and stream re-establishment
- Water quality treatment






BUILDING STRONG®

Stream Restoration





- 1.5 AC Wetland Restoration
- 3,000 LF Stream (I & E) Restoration:

stream re-establishment & enhancement

5.0 Acres Riparian Forest





Stream Restoration



Cumberland River Watershed: Buck Creek Stream Restoration


1,240 LF Stream enhancement, rehabilitation and re-establishment.



BUILDING STRONG_®

Stream Restoration






Big Sandy River Watershed: EF #2 Little Sandy Stream Restoration



Stream Restoration



Big Sandy River Watershed: Laurel Gorge WMA

■ 83,000 LF Stream (P, I, E) & 700 AC Watershed Preservation

Applied Stream Overview

 Stream Facts, Regulatory Review & Stream Definition

- Examples of Degraded Streams
- Sources of Stream Impacts
- Compensating for Stream Impacts Stream Restoration

Questions?



